

# APPROVAL OF SERVICE SUPPLIERS

This is to certify that

**PRZEDSIĘBIORSTWO HANDLOWO TECHNICZNE SUPON S.A.**

**Straszyn, Poland**

is granted acceptance for

**Inspection and maintenance of fire extinguishing equipment and systems , in accordance with Class Programme DNVGL-CP-0484.**

This service supplier certificate will be accepted for use with all rule sets published by DNV GL.  
**See the following page(s) for details regarding application.**

This Certificate is valid until **2019-07-12**.

Issued at **Gdansk CMC** on **2016-07-13**



for **DNV GL**

This document has been digitally signed and  
will therefore not have handwritten signatures

**Wisniewski, Jacek**  
**Principal Surveyor**

This Certificate may be withdrawn if:

1. The service provided has been improperly carried out or the results improperly reported.
2. The surveyor has found any deficiencies in the accepted operating systems of the service supplier.
3. The firm has failed to inform of any major changes having effect on the quality of the service rendered.
4. The conditions listed in the certificate are changed and/or are not fulfilled.



Certificate No: **AOSS0000BGY**

**Application:**

1. Renewal audit performed by DNVGL Gdansk on 2016-07-12.
2. Scope of approval:
  - CO2 High Pressure, Fixed Fire Fighting Systems
  - Halon , Fixed Fire Fighting Systems
  - Foam, Fixed Fire Fighting Systems
  - Portable and Wheeled Fire Extinguishers
  - Fire Hoses and Associated Equipment

# APPROVAL OF SERVICE SUPPLIERS

This is to certify that

**PRZEDSIĘBIORSTWO HANDLOWO TECHNICZNE SUPON S.A.**

**Straszyn, Poland**

is granted acceptance for

**Inspections and maintenance of self-contained breathing apparatus , in  
accordance with Class Programme DNVGL-CP-0484.**

This service supplier certificate will be accepted for use with all rule sets published by DNV GL.

This Certificate is valid until **2019-07-12**.

Issued at **Gdansk CMC** on **2016-07-13**



for **DNV GL**

This document has been digitally signed and  
will therefore not have handwritten signatures

**Wisniewski, Jacek**  
**Principal Surveyor**

This Certificate may be withdrawn if:

1. The service provided has been improperly carried out or the results improperly reported.
2. The surveyor has found any deficiencies in the accepted operating systems of the service supplier.
3. The firm has failed to inform of any major changes having effect on the quality of the service rendered.
4. The conditions listed in the certificate are changed and/or are not fulfilled.